

The room was first used for homework and also to eat. Now with the addition of the covered courtyard, is only used as a refectory.

Our interventions: restoration and painting of walls and ceiling, demolition of a wall unused closet, new floor, tiling walls, creating new tables and benches, painting doors and windows, replacement of glass windows and curtains.

{gallery}agragallery/salapranzo{/gallery}